


Sep.1.2024 Copyright 2024 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.



NOTE 1 Do not apply any excessive stress to the cable assembly position.

2	ML51-LP-DTR178-D(40)	CL337-0054-0-40					
1	HRM-200-066PBN(40)	CL323-0791-6-40	3	A12B0733-01	Junkosha Inc.		
NO.	PART NO.	CODE NO.	NO.	PART NO.	MANUFACTURER		
UNITS mm		SCALE FREE	COUNT 	DESCRIPTION OF REVISIONS	DESIGNED	CHECKED	DATE
HRS HIROSE ELECTRIC CO., LTD.				APPROVED : TO. KATAYAMA 20190611	DRAWING NO. EDC-388931-01-00		
				CHECKED : TO. KATAYAMA 20190611	PART NO. HRMP-ML51LP-066J1-B-300		
				DESIGNED : NK. OOSAWA 20190611	CODE NO. CL321-1720-0-01		
				DRAWN : ST. KISHI 20190611			